

Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)



Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)




Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)



Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)



Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)



Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)



Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)



Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)



Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)



Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)




Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)



Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)



Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)



Appendix D Other Offset Area Photos

Annual Compliance Report





A-Main entrance gate, B-Waterway barrier crossing, C-Access track and D-Fence with visibility tags

Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)

Annual Compliance Report

Erosion within offset access track





Woolooga Solar Farm, Lower Wonga, Queensland (EPBC 2019/8554)





A-Erosion point 1, B-Erosion point 2, C-Erosion point 3, D-Erosion point 4, E-Erosion point 5, F-Erosion point 6 and G-Erosion point 7.

Woolooga Solar Farm,

Lower Wonga, Queensland
(EPBC 2019/8554)